


INSTRUCTIONS FOR USE - PDC head lice comb

For detecting and removal of head lice, eggs and nits.

- 1. Brush any snarls or tangles out of the hair prior to combing
- 2. Comb one section of hair (comb wide) at a time, from root to tip
- 3. Wipe off any lice, eggs or nits on the comb with a tissue
- 4. Continue to comb until no more lice can be found







Hold front of the comb (marked CE) towards the head.



Do not use if damaged or miscoloured. Do not boil.

This product is a medical device.

If any serious incident has occurred in relation to the use of the comb, you should report it to the distributor, the manufacturer and/or the competent local medical device authority.

Made in Germany.

Material: ABS.

















Zantey ApS • Lejrvej 17 • 3500 Værløse • Denmark • www.zantey.com

Distribution by:

Zantey ApS IFU PDC Rev. 20230309 005